



ID	10 (TDMS Dateiname).tdms	Attribute	Value
	Loss (GBP/a)	1,83	
	Leak rate (cfm)	0,00	
	Level (dB)	51,7	
	Pressure (psi)	87	
	Distance (ft)	0,69	
	Gas type	Air	
	Machine	C-14	
	Component	W-Einheit	
	Priority	4	
	Repair recommended	Yes	
	Repair done	Yes	
	Repairman	Müller	
Repair date	02.02.2022		
Comment Teflonband erneuern			

ID	11.tdms	Attribute	Value
	Loss (GBP/a)	13,07	
	Leak rate (cfm)	0,03	
	Level (dB)	67,5	
	Pressure (psi)	87	
	Distance (ft)	0,95	
	Gas type	Air	
	Machine	Lack 22	
	Component	M 12	
	Priority	3	
	Repair recommended	Yes	
	Repair done	No	
	Repairman		
Repair date			
Comment Absperrung erneuern			